



Department of Energy

ROCKY FLATS FIELD OFFICE  
10808 HIGHWAY 93, UNIT A  
GOLDEN, COLORADO 80403-8200

AUG 22 2000

00-DOE-03228


Mr. Steve Gunderson  
Rocky Flats Cleanup Agreement Project Coordinator  
Colorado Department of Public Health and Environment  
4300 Cherry Creek Drive South  
Denver, CO 80222-1530

Dear Mr. Gunderson:

Please find enclosed the revised Reconnaissance Level Characterization Report for the Building 707 Cluster, Revision 1, August 1, 2000. The Building 707 Cluster includes buildings 707, 778, T707S Oil Storage Shed, 708 Air Compressor and Emergency Generator Building, Buildings 711, 711A, and 718 Cooling Tower, Cooling Tower Emergency Diesel Pump and Cooling Tower Pump House, Building 731 Plenum Deluge/Process Waste Pit, 707 tanks, and Building 732 and 778 laundry tank and pump vault.

The enclosed report is resubmitted for your concurrence. Also enclosed are the responses to each of your comments. The report has been revised to address your comments as appropriate. All facilities in the 707 Cluster are characterized as Rocky Flats Cleanup Agreement Type 1 and 2 facilities, except Building 707 which is a Type 3 facility. Please make note that the enclosures are Unclassified Controlled Nuclear Information and are not for public dissemination. Your concurrence will be assumed 14 days from the date of this letter unless your non-concurrence is communicated within that period of time.

Sincerely,

  
for Joseph A. Legare  
Assistant Manager  
for Environment and Infrastructure

Enclosures

When separated from enclosures,  
handle this document as unclassified/  
*not UCNI/not CUC*

1/1  
JAN 2001  
RECEIVED  
RECORDS CENTER

*OK for public release.*  
*QA Nesheim - 07-03-08*  
*EMCBC Classin*

ADMIN RECCRD

B707-A-000019